



BRINGELANDS MASKINHANDEL AB
CERTIFIED PRE-AUCTION INSPECTION

• VERIFIED

REPORT INSP-2026-10-SK714

INSPECTION REPORT

2020 KOMATSU SK714-5

Compact Skid Steer Loader · Stock No. 354803177

INSPECTION DATE

03 Oct 2026

ENGINE HOURS

118 h

INSPECTOR

J. Janssens

CERTIFICATION

BE-MECH-5512



ESSENTIALLY NEW – PASSED INSPECTION

Comprehensive on-site inspection completed by a certified heavy-machinery mechanic. With only **118 hours**, this machine is in near-new condition. Engine, hydraulics, transmission, cab, electrical, and all attachments were tested under no-load and light-load conditions. All systems operate to specification. No faults found.



MACHINE IDENTIFICATION

PIN

KMTSK004ELLUF05391

CATEGORY

Compact Skid Steer Loader

MODEL NUMBER

SK714-5

YEAR OF MANUFACTURE

2020

MANUFACTURER

Komatsu Ltd., Japan

CURRENT LOCATION

Overijse, Belgium



KEY SPECIFICATIONS

OPERATING MASS	2,670 kg
RUNNING HOURS	118 m/h
ENGINE	Komatsu Diesel
POWER	34.9 kW (47 hp)
TRANSMISSION	Automatic
WHEELS	10-16.5
ATTACHMENTS	4-in-1 bucket with teeth, pallet forks, U.Emme sweeper
CONDITION	Used
MAINTENANCE	Done
YEAR OF MANUFACTURE	2020



OPERATIONAL TEST LOG

COLD START	✓ Instant, no smoke
WARM IDLE (10 MIN)	✓ Stable, no misfire
LOADER CYCLE (FULL RANGE)	✓ Smooth, no drift
4-IN-1 BUCKET FUNCTION	✓ Correct operation
PALLET FORK FUNCTION	✓ Correct operation
U.EMME SWEEPER FUNCTION	✓ Correct operation
3RD FUNCTION	✓ Functional
STEERING (LOCK TO LOCK)	✓ Responsive
BRAKE TEST	✓ Firm pedal
TRANSMISSION (FORWARD/REVERSE)	✓ No slip
HEATING SYSTEM	✓ Functional
ROAD LIGHTING & BEACON	✓ All functional

FLUID CONDITION REPORT

ENGINE OIL	✓ Clean, correct level
ENGINE COOLANT	✓ Clean, no contamination
HYDRAULIC FLUID	✓ Clean, correct level
TRANSMISSION FLUID	✓ Clean, correct level
AXLE OIL (FRONT/REAR)	✓ Clean, correct level
FUEL SYSTEM	✓ No water, no sediment

01 / ENGINE & POWERTRAIN

— ENGINE BAY — KOMATSU DIESEL

The **Komatsu diesel engine** was inspected cold and again after warm-up. Cold start is instant and clean; idle is stable and the engine runs smooth through the entire RPM range. A full visual inspection of the engine bay shows **no oil leaks, no coolant seepage, and no fuel weepage**. Belts and hoses are in as-new condition. Air filter element is clean. No fault codes present. The engine bay is dry and spotless. The machine reads **118 hours** on the original working hour meter — consistent with a nearly new machine.

02 / HYDRAULIC SYSTEM

— MAIN & AUXILIARY HYDRAULIC PUMPS

The full hydraulic system was operated under load. **All cylinders, hoses, and fittings are dry and leak-free**. The **main hydraulic pump** and **auxiliary hydraulic system** are both reported in excellent condition. Loader lift and dump cycle smoothly with no drift. The **3rd function** and **universal quick hitch** engage and lock correctly. Hydraulic fluid is clean and at the correct level. No weeping at any gland seals or connections.

03 / CAB & OPERATOR STATION

— CAB INTERIOR, CONTROLS & INSTRUMENTATION

The **cab interior is clean, dry, and free of damage**. All operator controls — loader levers, auxiliary function controls, foot pedals, steering, and throttle — were verified to function smoothly through their full range. The instrument cluster, hour meter, warning lights, and gauges all operate correctly. The **front door** and **heating system** function correctly. The **seat and seatbelt** and **windshield** are both reported in excellent condition. Road lighting and beacon are functional.

04 / AXLES, FRAME & UNDERCARRIAGE

— CHASSIS, PINS, BUSHINGS, AXLES & BRAKES

The axles, frame, and undercarriage were inspected visually and operationally. **Pins and bushings are in as-new condition with negligible wear** — no significant play was detected. The **axles** and **brakes** are both reported in excellent condition. The main frame and subframe are straight, sound, and free of any structural damage or cracking. No rust perforation or impact damage anywhere on the chassis. The **additional counterweight (126 kg)** is securely mounted.

05 / TIRES & WHEELS

— TIRE CONDITION – 10-16.5


All four tires are in **excellent condition with approximately 95% tread remaining**. Tires (10-16.5) show even wear across the tread face with no flat spots, cupping, or irregular wear patterns. Sidewalls are intact with no cuts, gouges, or bulge damage. Rims and wheels are straight, clean, and free of cracks or rust.

06 / LOADER ARMS & ATTACHMENTS

— LOADER ARMS, LINKAGE, BUCKET & ATTACHMENTS

The **loader arms and linkage** operate smoothly through full range with no binding. Pins and bushings at the loader pivot points show **as-new condition with no excessive play**. The **4-in-1 bucket with teeth** is in excellent condition with the cutting edge showing minimal wear. The **pallet forks** are in excellent condition with straight tines. The **U.Emme collector sweeper 1550 HD** is in excellent condition and functions correctly. The **universal quick hitch** engages and locks correctly with no excessive play.

PHOTO INDEX – MACHINE REFERENCE



REFERENCE 01




REFERENCE 02



REFERENCE 03



REFERENCE 04



REFERENCE 05



REFERENCE 06



REFERENCE 07




REFERENCE 08




REFERENCE 09



REFERENCE 10



REFERENCE 11




REFERENCE 12



REFERENCE 13



REFERENCE 14



REFERENCE 15

✓ WHAT YOU GET WITH THIS MACHINE



FREE DELIVERY

First **500 km free** — then just **€1 / km**.



FULLY INSURED

Fully insured during transport across all of Europe.



6-MONTH WARRANTY

6 months across Europe — extendable to 5 years.



14-DAY REFUND

14 days to inspect on arrival. Full refund if not as described.



VERIFIED SELLER

Bolagsverket-registered. **Org.nr 559155-3432**.



FULL DOCUMENTATION

Ready to register in the new owner's name.

JAN JANSSENS

CERTIFIED HEAVY-MACHINERY MECHANIC

Certification No. **BE-MECH-5512**

Belgian Heavy Equipment Institute

03 OCTOBER 2026

DATE OF INSPECTION

Report No. **INSP-2026-10-SK714**

Location: **Overijse, BE**

Inspector statement & disclaimer: This machine was inspected on 03 October 2026 by a certified heavy-machinery mechanic. Operational tests were performed under no-load and light-load conditions. All findings reflect the condition of the machine on that date and represent a good-faith assessment. The buyer has a 14-day post-delivery inspection window to independently verify the machine on arrival, with full refund protection under our refund policy. Final sale price is confirmed at auction close.

BRINGELANDS MASKINHANDEL AB

ORG.NR 559155-3432 · VAT SE559155343201

ADLER SALVIUS GATA 15 · 411 11 GÖTEBORG · SWEDEN

BRINGELANDSMASKINHANDELAB.COM



SCAN TO VIEW
THIS MACHINE